

1200 E. 151<sup>st</sup> Street Olathe, KS 66062 913-397-8200

# SERVICE ADVISORY

NO.: 23040 Rev A

TO:G1000 NXi Embraer 500 and 505 Owners and OperatorsDATE:April 25, 2023

SUBJECT: TA/RA Triggered On Ground

## PRODUCTS AFFECTED

G1000 NXi-equipped Embraer EMB-500 Phenom 100 and EMB-505 Phenom 300 aircraft with system software version 3643.06 (or earlier) installed under STC SA01933WI with ACSS TCAS II and KRA 405B are affected.

## <u>ISSUE</u>

TA/RAs are triggered on the ground during RADALT initialization.

## **PILOT ACTION**

After starting the avionics, make sure TCAS is in Standby mode.

Activate TCAS when on the runway.

### RESOLUTION

The nuisance RADALT behavior will be addressed in a future software release.

© 2023 Garmin Ltd. or its subsidiaries. This work is licensed under a <u>Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.</u>

Service Advisory 23040 April 25, 2023 Page 1-1 Revision A