

1200 E. 151<sup>st</sup> Stree Olathe, KS 66062 913-397-8200

#### **AVIATION SERVICE DOCUMENT NOTIFICATION**

TO: G1000® Phenom EMB-500 and EMB-505 Aircraft Aircraft Owner and Operators

**DATE:** October 28, 2022

SUBJECT: G1000 NXi STC Software Update for Phenom EMB-500 and EMB-505 Aircraft

**CERTIFICATION** 

**AUTHORIZATION:** STC SA01933WI

## **COMPLIANCE**

Optional: STC Service Bulletin 22093 may be incorporated at the owner's discretion.

## **PURPOSE**

This service bulletin provides notification for System Software Version 3643.06 and provides the following:

- GTX<sup>™</sup> 345(D)R ADS-B system software update to version 3.14 for improved 1090ES ADS-B/ ADS-R/TIS-B message reception processing (applicable to EMB-500 only)
- Audio configuration update to provide improved audio output in support of the optional CVR (use and approval are the responsibility of the installer); refer also to Service Bulletin 22092.
- New option to enable ATC audio to the cabin (GMA™ 1360D installations)
- Configuration update to correct brake pressure parameter display on the OEM Diagnostics page
- Configuration update to allow changes to the default page navigation timeout setting
- Emergency Descent Mode (EDM) improvement to switch transponder code to 7700 with EDM activation
- EDM configuration updated to set airspeed reference upper limit to 275 knots (EMB-500) and 250 knots (EMB-505)

# **PRODUCTS AFFECTED**

Embraer S.A EMB-500 (Phenom 100) and EMB-505 (Phenom 300) aircraft equipped with G1000 NXi Integrated Flight Deck installed per AML STC SA01933WI System Software Version 3643.00 thru 3643.04 are affected.



#### NOTE

System Software Version 3643.05 will never be released.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.