



GO BEYOND

2021 ESP™ PROGRAM RATES

Embraer Phenom 100EV

PW617F1-E

	GOLD LITE	GOLD	PLATINUM
Early Enrollment	\$155.75	\$175.40	\$196.15
Basic	\$173.05	\$194.90	\$217.95

Services	GOLD LITE	GOLD	PLATINUM
Engine Overhaul or Refurbishment	■	■	■
Hot Section Inspection (HSI)	■	■	■
Basic Unplanned Engine Removal (BUER)	■	■	■
Basic Unplanned Accessory Removal (BUAR)	■	■	■
Troubleshooting Labour	■	■	■
Service Bulletin Incorporation [Cat 1-6]	■	■	■
Lease Engine Support	■	■	■
Trend Monitoring	■	■	■
LCF component replacement		■	■
Removal and Installation (R&I)	■	■	■
Mobile Repair Team (MRT) for AOG	■	■	■
Freight	■	■	■
Routine Periodic Inspections *			■
Low Utilization Inspections			■
Engine Wash (one per year)			■
Environmental Damage Repair			■
Oil Analysis	■	■	■

**GET PEACE OF MIND
ENROLL TODAY**

NO ANNUAL MINIMUMS

For information or to enroll contact:

your local [Sales Representative](#)

or

ESP Frontline

+1 (800) 268-8000, Option 2 or

+1 (450) 647-8000, Option 2

or

GetESP@pwc.ca

For transfers, email:

ESP.admin@pwc.ca

All rates are per engine, per hour and in USD\$. Applicable taxes are excluded. Rates are subject to annual adjustment.

Rates are based on an average mission of 60 minutes or greater (6-month rolling average).

Early Enrollment rate available when enrolling with less than 200 TTSN. Early Enrollment rate applicable up to 1000 TTSN.

* Does not include pre-flight inspections.